

| Chimacum Creek Primary School | | | Received Report 1/16/2020 | | | | | |
|--|------------|------------|--|-----------|--|-----------|----------|---|
| Date/Results | 11/26/2019 | 11/27/2019 | Action Taken | 1/15/2020 | Action Taken: | 2/26/2020 | 3/3/2020 | Action Taken: |
| Test | Lead | Lead | | Lead | Retest end of February | Lead | Lead | School Closed 3/17/2020 |
| Samples Collected By | DOH | DOH | | DOH | | DOH | DOH | |
| Location: | | | | | | | | |
| RM 506: Kitchen Sink | 22 | | Fixutre replaced, retest on 1/11/2020 | 29 | Replaced parts - 1/24/20, 1/27/20 | | | |
| Kitchen single sink - First Draw | | | | | | TB | 2 | |
| Kitchen single sink - Flush | | | | | | 4 | | |
| RM 506: Kitchen sink: pot filler/spring spout - First Draw | | | | 21 | Replaced spring sprayer - 1/24/20, 1/27/20 | 5 | | |
| RM 506: Kitchen sink: pot filler/spring spout - Flush | | | | | | 1 | | |
| RM 506: Kitchen Double Sink | 8 | | Aerator replaced 12/19 | 8 | Replaced Fixture - 1/24/20, 1/27/20 | | | |
| Kitchen double sink: pot filler/spring spout - First Draw | | | | 39 | Replaced Fixture - 1/24/20, 1/27/20 | 2 | | |
| Kitchen double sink: pot filler/spring spout - Flush | | | | | | <1 | | |
| Kitchen double sink right tap - First Draw | | | | | | 5 | | |
| Kitchen double sink right tap - Flush | | | | | | <1 | | |
| Kitchen double sink: left tap - First Draw | | | | | | 15 | | Changed Head - 4/7/20. Flush sink everyday when used. |
| Kitchen double sink: left tap - Flush | | | | | | <1 | | |
| Bubbler/bottle filler combo near gym/breakfast room | <1 | | | | | | | |
| Bubbler/bottle filler combo near gym/breakfast room | <1 | | | | | | | |
| RM 501: Music room | 13 | | Aerator replaced 12/19. Flushed, retest on 1/11/2020 | 6 | | | | |
| Entrance bubbler/bottle filler combo | <1 | | | | | | | |
| Entrance bubbler/bottle filler combo | <1 | | | | | | | |
| Health room 105 | 11 | | Aerator replaced 12/19. Flushed, retest on 1/11/2020 | 12 | Replaced Fixture - 1/24/20, 1/27/20 | 2 | | |

| Chimacum Creek Primary School | | | Received Report 1/16/2020 | | | | | |
|--|------------|------------|---|-----------|--|-----------|----------|---------------------------|
| Date/Results | 11/26/2019 | 11/27/2019 | Action Taken | 1/15/2020 | Action Taken: | 2/26/2020 | 3/3/2020 | Action Taken: |
| Test | Lead | Lead | | Lead | Retest end of February | Lead | Lead | School Closed 3/17/2020 |
| Samples Collected By | DOH | DOH | | DOH | | DOH | DOH | |
| Location: | | | | | | | | |
| Library office room 401 | 13 | | Aerator replaced 12/19. Flushed, retest on 1/11/2020 | 9 | | | | |
| Staff lounge room 111 | 9 | | Aerator replaced 12/19 | 6 | | 5 | | |
| RM 109: Staff work room | | | | 17 | Replaced Fixture - 1/24/20, 1/27/20 | | | |
| RM 301 | 14 | | Aerator replaced 12/19. Flushed, retest on 1/11/2020 | 15 | Replaced Fixture - 1/24/20, 1/27/20 | 16 | | Replaced Faucet - 4/7/20. |
| RM 303 | 3 | | Aerator replaced 12/19 | 4 | | | | |
| RM 304 | 12 | | Aerator replaced 12/19 | 7 | | | | |
| RM 306 | 3 | | Aerator replaced 12/19 | 2 | | | | |
| RM 308 | 4 | | Aerator replaced 12/19 | 4 | | | | |
| RM 305 | 8 | | Aerator replaced 12/19 | 6 | | | | |
| RM 309 | 3 | | Aerator replaced 12/19 | 4 | | | | |
| RM 311 | 6 | | Aerator replaced 12/19 | 6 | | | | |
| Tap adjacent to rm 311 | 11 | | Aerator replaced 12/19 | 9 | | | | |
| RM 310 | 4 | | Aerator replaced 12/19 | 3 | | | | |
| RM 312 | 5 | | Aerator replaced 12/19 | 3 | | | | |
| Bubbler/bottle filler combo adjacent to boys rr; nearest rooms 311/312 | <1 | | | | | | | |
| Bubbler/bottle filler combo adjacent to boys rr; nearest rooms 311/312 | <1 | | | | | | | |
| RM 204 low tap | 7 | | Aerator replaced 12/19 | 6 | | | | |
| RM 204 high tap | 10 | | Aerator replaced 12/19 | 5 | | | | |
| RM 208 | 17 | | Aerator replaced 12/19. Flushed, retest on 1/11/2020 | 19 | Replaced Fixture - 1/24/20, 1/27/20 | 8 | | |
| RM 210 | 9 | | Aerator replaced 12/19 | | | | | |
| RM 210: low sink | | | Aerator replaced 12/19 | 10 | | | | |
| RM 210: high sink/double sink | | | | 26 | Replaced Fixture - 1/24/20, 1/27/20 | | | |
| RM 207: right tap | | 10 | Aerator replaced 12/19 | 7 | | | | |
| RM 207: left tap | | | | 3 | | | | |
| RM 211: high sink/double sink | | 7 | Aerator replaced 12/19 | 14 | Replaced Fixture - 1/24/20, 1/27/20 | 8 | | |
| RM 211: low single sink tap | | 5 | Aerator replaced 12/19 | 5 | | 2 | | |

| Chimacum Creek Primary School | | | | | | | | |
|---|------------|------------|---|-----------|--|-----------|----------|-------------------------|
| Date/Results | 11/26/2019 | 11/27/2019 | Action Taken | 1/15/2020 | Action Taken: | 2/26/2020 | 3/3/2020 | Action Taken: |
| Test | Lead | Lead | | Lead | Retest end of February | Lead | Lead | School Closed 3/17/2020 |
| Samples Collected By | DOH | DOH | | DOH | | DOH | DOH | |
| Location: | | | | | | | | |
| Kindergarten wing kitchenette sink | | 14 | Aerator replaced 12/19. Flushed, retest on 1/11/2020 | 17 | Replaced Fixture - 1/24/20, 1/27/20 | 5 | | |
| Kindergarten wing bubbler/bottle filler combo | | <1 | | | | | | |
| Kindergarten wing bubbler/bottle filler combo | | <1 | | | | | | |