

Chimacum Elementary School			Received Report 1/30/2020						
	Date/Results	11/27/2019	12/6/2019	Action Taken	1/14/2020	1/16/2020	Action Taken	2/26/2020	3/3/2020
Test	Lead	Lead		Lead	Lead	Retest end of February	Lead	Lead	
Samples Collected By	DOH	DOH		DOH	DOH		DOH	DOH	
Location:									
RM 503		5	Aerator replaced 12/19		3				
RM 504		2	Aerator replaced 12/19			4			
RM 505		2	Aerator replaced 12/19		2				
RM 506		2	Aerator replaced 12/19		1				
RM 502		4	Aerator replaced 12/19			3			
STAFF RM 501		1	Aerator replaced 12/19						
STAFF RM 507/512; tap adjacent to dishwasher		9	Aerator replaced 12/19		7				
Conference RM 511		3	Aerator replaced 12/19		1				
RM 606		2	Aerator replaced 12/19		9				
RM 601		2	Aerator replaced 12/19		2				
RM 605		1	Aerator replaced 12/19						
RM 602		3	Aerator replaced 12/19		1				
RM 603		3	Aerator replaced 12/19		1				
RM 604		7	Aerator replaced 12/19		4				
Bubbler/bottle filler adjacent ladies room of grades 6-PI wing		<1							
Bubbler/bottle filler adjacent ladies room of grades 6-PI wing		<1							
RM 406		19	Fixture replaced, retest 1/11/2020.		3				
RM 409 - front tap		10	Aerator replaced 12/19		5				
RM 409 - tap next to microwave - First Draw					8		Tagged as non-potable water - Science - 2/3/2018		
RM 409 - tap next to microwave - Flush					9		Tagged as non-potable water - Science - 2/3/2018		
RM 408 adjacent to eyewash		7	Aerator replaced 12/19		4				
RM 408 back wall left tap		4	Aerator replaced 12/19		4				
RM 408 back wall right tap		2	Aerator replaced 12/19		1				

Chimacum Elementary School				Received Report				
Date/Results	11/27/2019	12/6/2019	Action Taken	1/14/2020	1/16/2020	Action Taken	2/26/2020	3/3/2020
Test	Lead	Lead		Lead	Lead	Retest end of February	Lead	Lead
Samples Collected By	DOH	DOH		DOH	DOH		DOH	DOH
Location:								
Bubbler/bottle filler near double doors labeled 431	<1		Aerator replaced 12/19					
Bubbler/bottle filler near double doors labeled 431	<1		Aerator replaced 12/19					
RM 704: Elementary food service double sink tap - First Draw	9		Aerator replaced 12/19	7			5	
RM 704: Elementary food service double sink tap - Flush							2	
RM 704: Elementary food service sink: pot filler/spring spout				11		Spring Sprayer replaced - 2/3/2020		
RM 704: Elementary food service single back sink - First Draw	109		Parts replaced, retest 1/11/2020.	52		Replaced entire unit - 2/3/2020	TB	7
RM 704: Elementary food service single back sink - Flush				8		Replaced entire unit - 2/3/2020	2	
RM 704: Elementary food service single back sink: pot filler/spring sprout				11		Spring Sprayer replaced - 2/3/2020	3	
Elementary food service hand wash sink				7				
Elementary office bubblers: high	1							
Elementary office bubblers: low	1							
RM 727: Office health room	10		Aerator replaced 12/19	4				
Office RM 730	5		Aerator replaced 12/19	5				
RM 701: Band Room	4		Aerator replaced 12/19	4				
Performing Arts wing; low bubbler	<1							

Chimacum Elementary School								
Date/Results	11/27/2019	12/6/2019	Action Taken	Received Report		Action Taken	2/26/2020	3/3/2020
Test	Lead	Lead		Lead	Lead	Retest end of February	Lead	Lead
Samples Collected By	DOH	DOH		DOH	DOH		DOH	DOH
Location:								
Performing Arts wing bubbler/bottle filler	<1							
Performing Arts wing bubbler/bottle filler	<1							
Multi purpose room: kitchen double sink		15	Aerator replaced 12/19	12		Kitchen closed - non potable use - 1/3/2020		
Multi purpose room: kitchen triple sink left tap		62	Aerator replaced 12/19	37		Kitchen closed - non potable use - 1/3/2020		
Multi purpose room: kitchen triple sink right tap		15	Aerator replaced 12/19	11		Kitchen closed - non potable use - 1/3/2020		
Multi purpose room kitchen pot filler/spring spout at back in room with triple sink				5		Kitchen closed - non potable use - 1/3/2020		
Multi purpose room kitchen double sink pot filler/spring spout				6		Kitchen closed - non potable use - 1/3/2020		
Multi purpose room bubbler/bottle filler	<1		Aerator replaced 12/19					
Multi purpose room bubbler/bottle filler	<1		Aerator replaced 12/19					